
CLEANING AND DISINFECTING GUIDELINES FOR MOTOROLA SOLUTIONS DEVICES

RADIOS, BODY WORN CAMERAS AND ACCESSORIES

Motorola Solutions is providing recommended cleaning and disinfecting guidelines for our radios, body-worn cameras and accessories based on our current and best understanding of radio hygiene.



Per global health authorities, removing germs, dirt and impurities from surfaces lowers the risk of spreading infection. Using chemical disinfectants may kill germs that remain on surfaces after cleaning, which further lowers the risk of spreading infection. Motorola Solutions, Inc. is unable to, and did not, determine whether any particular cleaning product is effective in removing specific foreign substances (including viruses) from the device, nor whether any disinfectant will remove all germs or viruses. However, the above cleaners, disinfectants and processes have been approved for use by Motorola Solutions, Inc. related to their less degrading effect on the physical device. Please consult the chemical manufacturers' documentation for specifics on cleaning product efficacy with regards to foreign substances (such as viruses).

To consult the official Motorola Solutions Technical Notification, **click here.**

Information from the WHO website: <u>Getting your workplace ready for COVID-19</u>
Information from the US CDC website: <u>Coronavirus Disease 2019 (COVID-19)</u>

For additional assistance, please contact the appropriate Motorola Solutions Technical Support Center:

AMERICAS: www.motorolasolutions.com/en_us/support.html

EMEA: <u>www.motorolasolutions.com/en_xu/support.html</u>
APAC: <u>www.motorolasolutions.com/en_xp/support.html</u>



Motorola Solutions, Inc. 500 West Monroe Street, Chicago, II 60661 U.S.A. motorolasolutions.com

ANY USE NOT APPROVED BY MOTOROLA SOLUTIONS IS PROHIBITED. This is an adaptation of the Motorola Solutions technical Notification (MTN), that can be consulted on the link above. The information provided here is intended for use by trained, professional technicians only, who have the expertise to perform the service described in the MTN. Motorola Solutions disclaims any and all liability for product quality or performance if the recommendations are not implemented, or not implemented in compliance with the instructions provided here. Implementation of these recommendations may be necessary for the product to remain compliant with applicable laws or regulations. Please be advised, that failure to implement these recommendations in the manner instructed may also invalidate applicable warranties, or otherwise impact any potential contractual rights or obligations. MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2020 Motorola Solutions, Inc. All rights reserved. ISSUE DATE: 03-2020